

**GOVERNMENT OF ANDHRA PRADESH**  
**ABSTRACT**

Natural Calamities – Panchayat Raj Department - LAILA Cyclone, May 2010 – Repairs & Additional Accommodation of Building works in 15 Districts – Administrative Sanction accorded – Orders – Issued.

**PANCHAYAT RAJ & RURAL DEVELOPMENT(PROGS.III) DEPARTMENT**  
**G.O.Rt.No. 1816**

**Dated:-30.11.2010.**

**Read the following:**

1. G.O.Rt.No.189 Revenue (DM.I) Dept. dated 8.6.2010
2. G.O.Rt.No.229 Revenue (DM.I) Dept. dated 5.7.2010
3. From the C.E (PR), Hyderabad Lr.No. AEE10/PR/Laila Cyclone/May 2010,  
Dated:27.10.2010.

&&&

**ORDER:**

In the reference 1<sup>st</sup> read above, the Revenue (DM.I) Department have accorded administrative sanction for an amount of Rs.115.96 crore to Panchayat Raj Department for attending to repair works to Roads and Buildings affected by Laila Cyclone.

2. In the reference 3<sup>rd</sup> read above, the Chief Engineer (PR), Hyderabad has submitted proposals for Repairs & Additional Accommodation of 220 Building works in 15 Districts i.e. Ananthapuram, Chittoor, East Godavari, Guntur, Kadapa, Khammam, Krishna, Nalgonda, Prakasam, Rangareddy, SPSR Nellore, Srikakulam, Visakhapatnam, Vizianagaram & West Godavari for an amount of Rs.1560.16 lakh for according administrative sanction.
3. Government after careful examination of the proposal hereby accord administrative sanction of Rs.1560.16 lakh for Repairs and Additional Accommodation of 220 Building works in 15 Districts i.e. Ananthapuram, Chittoor, East Godavari, Guntur, Kadapa, Khammam, Krishna, Nalgonda, Prakasam, Rangareddy, SPSR Nellore, Srikakulam, Visakhapatnam, Vizianagaram & West Godavari due to LAILA Cyclone as per the details of works in the Annexure-I appended to this G.O.
4. The Chief Engineer, Panchayat Raj, Hyderabad is requested to take necessary action accordingly.
5. A copy of these orders is available on the internet and can be accessed at the address: <http://www.ap.gov.in/goir>.

( BY ORDER AND IN THE NAME OF THE GOVERNOR OF ANDHRA PRADESH )

M.V.P.C SASTRY  
SPECIAL CHIEF SECRETARY TO GOVERNMENT

To  
The Chief Engineer, Panchayat Raj, Hyderabad.  
The Accountant General, A.P., Hyderabad.

Copy to:  
The OSD to Minister (P.R.).  
The Finance (Expr.PR&RD) Dept.  
SF/SC.

// FORWARDED :: BY ORDER //

SECTION OFFICER

**ANNEXURE TO THE GO.Rt.No.1816 Date.30-11-2010**

<b>Sl. No.</b>	<b>District</b>	<b>Constituency</b>	<b>Division</b>	<b>Mandal</b>	<b>Name of the work</b>	<b>Est. Cost Rs. in Lakhs</b>
1	Ananthapur	Ananthapur	Ananthapur	Ananthapur	Repairs & additional accomadation of Q.C. Laboratory cum office building at Ananthapur	18.00
2	Ananthapur	Ananthapur	Ananthapur	Ananthapur	Repairs to circle office at Ananthapur	5.00
3	Ananthapur	Penukonda	Penukonda	Penukonda	Repairs & additional accomadation of Q.C. Laboratory cum office building at Penukonda	18.00
4	Ananthapur	Madakasira	Penukonda	Penukonda	Repairs & Providing Additional Accommodataion to PR PIU Sub-Division, Madakasira	12.00
5	Ananthapur	Kadiri	Penukonda	Kadiri	Repairs to PIU Sub-Division Kadiri	3.00
6	Ananthapur	Rapthadu	Ananthapur ( N )	Ananthapur	Repairs & Providing Additional Accommodataion to PR PIU Sub-Division I @ Ananthapur	12.00
7	Ananthapur	Rapthadu	Ananthapur ( N )	Ananthapur	Repairs & Providing Additional Accommodataion to PR PIU Sub-Division II @ Ananthapur	12.00
8	Ananthapur	Tadipatri	Ananthapur ( N )	Tadipatri	Repairs & Providing Additional Accommodataion to PR PIU Sub-Division, Tadipathri	12.00
9	Ananthapur	Uravakonda	Ananthapur ( N )	Uravakonda	Repairs & Providing Additional Accommodataion to PR PIU Sub-Division, Uravakonda	12.00
10	Chittoor	Chittoor	Chittoor	Chittoor	Repairs & additional accomadation of Q.C. Laboratory cum office building at Chittoor	18.00
11	Chittoor	GD Nellore	Chittoor	GD Nellore	Repairs & additional accomadation of new PRI Sub division office building at GD Nellore	12.00
12	Chittoor	Puthalapattu	Chittoor	Srikalahasti	Repairs & additional accomadation of new PRI sub division office building at Srikalahasti	12.00
13	Chittoor	Tirupathi	Tirupathi	Tirupathi	Repairs & additional accomadation of Q.C. Laboratory cum office building at Tirupathi	18.00
14	Chittoor	Tirupathi	Tirupathi	Chandragiri	Repairs & additional accomadation of new PIU office building at Chandragiri	12.00
15	Chittoor	Tirupathi	Tirupathi	Palameneru	Repairs & additional accomadation of new PRI sub Division office building at Palameneru	12.00

<b>Sl. No.</b>	<b>District</b>	<b>Constituency</b>	<b>Division</b>	<b>Mandal</b>	<b>Name of the work</b>	<b>Est. Cost Rs. in Lakhs</b>
16	East Godavari District	Amalapuram	Amalapuram	Amalapuram	Repairs & additional accomadation of PIU sub Division office building at Amalapuram	12.00
17	East Godavari District	Kakinada	Kakinada	Kakinada Municipal	Repairs & additional accomadation of PIU subdivision building at Kakinada	18.00
18	East Godavari District	Peddapuram	Kakinada	Peddapuram	Repairs to sub division office at Peddapuram	5.00
19	East Godavari District	Pitapuram	Kakinada	Pitapuram	Repairs to sub division office at Pitapuram	7.00
20	East Godavari District	Rajahmundry	Rajahmundry	Rajahmundry Municipal corporation	Repairs & additional accomadation of DEE QC office building at Rajahmundry	18.00
21	East Godavari District	Ramachandrapuram	Kakinada	Ramachandrapuram	Const. of PRI Sub Division @ Ramachandrapuram	12.00
22	East Godavari District	Kakinada	Kakinada	Karapa(M)	Repairs to Cyclone Shelter Building at Adinipudi H/o Gurajanapalli	1.00
23	East Godavari District	Kakinada	Kakinada	Karapa(M)	Repairs to Cyclone Shelter Building at Adinipudi H/o Gurajanapalli Main	1.00
24	East Godavari District	Kakinada	Kakinada	Karapa(M)	Repairs to Cyclone Shelter Building at Uppalanka	1.00
25	East Godavari District	Kakinada	Kakinada	Gollaprolu	Repairs to Cyclone Shelter Building at A.K.Mallavaram	1.00
26	East Godavari District	Kakinada	Kakinada	Gollaprolu	Repairs to Cyclone Shelter Building at A.P.Mallavaram	1.00
27	East Godavari District	Kakinada	Kakinada	U.Kothapalli	Repairs to Cyclone Shelter Building at Gorsa	1.05
28	East Godavari District	Kakinada	Kakinada	U.Kothapalli	Repairs to Cyclone Shelter Building at Komaragiri	1.00
29	East Godavari District	Kakinada	Kakinada	U.Kothapalli	Repairs to Cyclone Shelter Building at Gontivari Pakalu H/o Kondevaram	1.10
30	East Godavari District	Kakinada	Kakinada	U.Kothapalli	Repairs to Cyclone Shelter Building at Vakatippa	1.00
31	East Godavari District	Kakinada	Kakinada	U.Kothapalli	Repairs to Cyclone Shelter Building at Kuthukudumalli	1.05

<b>Sl. No.</b>	<b>District</b>	<b>Constituency</b>	<b>Division</b>	<b>Mandal</b>	<b>Name of the work</b>	<b>Est. Cost Rs. in Lakhs</b>
32	East Godavari District	Kakinada	Kakinada	U.Kothapalli	Repairs to Cyclone Shelter Building at Uppada-I	0.95
33	East Godavari District	Kakinada	Kakinada	U.Kothapalli	Repairs to Cyclone Shelter Building at Uppada-II	1.35
34	East Godavari District	Kakinada	Kakinada	U.Kothapalli	Repairs to Cyclone Shelter Building at Amenabad	1.40
35	East Godavari District	Kakinada	Kakinada	U.Kothapalli	Repairs to Cyclone Shelter Building at Ramannapalem	1.10
36	East Godavari District	Kakinada	Kakinada	U.Kothapalli	Repairs to Cyclone Shelter Building at Konapapupapeta-II H/o Ponnada	0.90
37	East Godavari District	Kakinada	Kakinada	Kakinada ®	Repairs to Cyclone Shelter Building at Light House peta.	1.00
38	East Godavari District	Kakinada	Kakinada	Kakinada ®	Repairs to Cyclone Shelter Building at H/p of Nemam	1.00
39	East Godavari District	Kakinada	Kakinada	Kakinada ®	Repairs to Cyclone Shelter Building at Suryaraopeta	1.00
40	East Godavari District	Kakinada	Kakinada	Kakinada ®	Repairs to Cyclone Shelter Building at Vakalapudi	1.00
41	East Godavari District	Kakinada	Kakinada	Thondangi	Repairs to Cyclone Shelter at ADDARIPETA	2.00
42	East Godavari District	Kakinada	Kakinada	Thondangi	Repairs to Cyclone Shelter at YERRAYYAPETA	2.00
43	East Godavari District	Kakinada	Kakinada	Thondangi	Repairs to Cyclone Shelter at DANAVAIAPETA	1.00
44	East Godavari District	Kakinada	Kakinada	Thondangi	Repairs to Cyclone Shelter at BUTCHIYYAPETA	2.00
45	Guntur	Bapatla	Tenali	Bapatla	Repairs & additional accomadation PRI Sub-Division Office building at Bapatla	12.00
46	Guntur	Guntur	Guntur	Guntur	Repairs & additional accomadation of QC Sub-Division Office building including Laboratary @	18.00
47	Guntur	Narasaraopet	Narasaraopet	Narasaraopet	Repairs & additional accomadation of QC Sub-Division Office building including laboratary @	18.00

<b>Sl. No.</b>	<b>District</b>	<b>Constituency</b>	<b>Division</b>	<b>Mandal</b>	<b>Name of the work</b>	<b>Est. Cost Rs. in Lakhs</b>
48	Guntur	Pedakurapadu	Guntur	Pedakurapadu	Repairs & additional accomadation of PRI Sub-Division Office building Pedakurapadu @	12.00
49	Guntur	Prathipadu	Guntur	Guntur Rural	Repairs & additional accomadation of PIU Sub-Division Office building Nallapadu @ Guntur	12.00
50	Guntur	Sattenapalli	Guntur	Sattenapalli	Repairs & additional accmadation of PRI sub diviison officebuilding at Sattenapalli	12.00
51	Guntur	Tadikonda	Guntur	Tadikonda	Repairs & additional accomadation of PRI Sub-Division Office building at Tadikonda @ Guntur	12.00
52	Guntur	Tenali	Tenali	Tenali	Repairs & additional accomadation of PIU Sub-Division Office building at Tenali	12.00
53	Kadapa	Jammalamadugu	Jammalamadugu	Jammalamadugu	Repairs & additional accomadation of PRI Sub division and Q.C. Laboratory cum office building at	30.00
54	Kadapa	Jammalamadugu	Jammalamadugu	Muddanur	Repairs & additional accomadation of PIU Sub division office new building at Muddanur	12.00
55	Kadapa	Kadapa	Kadapa	Kadapa	Repairs & additional accomadation of PRI Sub division and QC sub Division and lab office building	30.00
56	Kadapa	Kadapa	Kadapa	Kadapa	Repairs and renovation of P.R Circle Office at Kadapa	4.00
57	Kadapa	Kamalapuram	Kadapa	Kamalapuram	Repairs & additional accomadation of PRI Sub division office building at Kamalapuram	12.00
58	Kadapa	Rayachoty	Kadapa	Rayachoty	Repairs & additional accomadation of PRI Sub division office building at Rayachoty	12.00
59	Khammam	Ashraopeta	PIU Khammam	Aswaraopeta	Repairs & additional accomadation of PIU Sub-division Office at Aswaraopeta	12.00
60	Khammam	Bhadrachalam	PR Bhadrachalam	Bhadrachalam	Repairs & additional accomadation of Sub division offices PRI and QC lab cum office at Bhadrachalam	18.00
61	Khammam	Madhira	PIU Khammam	Madhira	Repairs to PIU SD Office at Madhira	5.00
62	Khammam	Pinapaka	PR Bhadrachalam	Burgumpahad	Repairs & additional accomadation of PIU Sub-division Office at Burgampahad	12.00
63	Khammam	Yellandu	PRI Khammam	Yellandu	Repairs to PRI SD Office at Yellandu	2.50

<b>Sl. No.</b>	<b>District</b>	<b>Constituency</b>	<b>Division</b>	<b>Mandal</b>	<b>Name of the work</b>	<b>Est. Cost Rs. in Lakhs</b>
64	Khammam	Yellandu	PRI Khammam	Kalluru	Repairs to PRI SD Office at Kalluru	2.50
65	Krishna	Avanigadda	Machilipatnam	Avanigadda	Repairs to sub division at Avanigadda	3.00
66	Krishna	Gannavaram	Vijayawada	Gannavaram	Repairs to sub division at Gannavaram	5.00
67	Krishna	Gudiwada	Machilipatnam	Gudiwada	Repairs to sub division at Gudiwada	2.00
68	Krishna	Jaggaiahpetta	Vijayawada	Jaggaiahpetta	Repairs to sub division at Jaggaiahpetta	4.00
69	Krishna	Kaikaluru	Machilipatnam	Mandavalli	Repairs to sub division at Mandavalli	4.00
70	Krishna	Machilipatnam	Machilipatnam	Machilipatnam	Repairs to SE Camp Office at Machilipatnam	4.00
71	Krishna	Machilipatnam	Machilipatnam	Machilipatnam	Repairs to sub division Vig&Qc at Machilipatnam	3.00
72	Krishna	Machilipatnam	Machilipatnam	Machilipatnam	Repairs to Division Office at Machilipatnam	3.00
73	Krishna	Machilipatnam	Machilipatnam	Machilipatnam	Repairs to sub division at Machilipatnam	2.00
74	Krishna	Mylavaram	Vijayawada	Mylavaram	Repairs to sub division at Mylavaram	4.00
75	Krishna	Nandigama	Vijayawada	Nandigama	Repairs to sub division at Nandigama	3.00
76	Krishna	Pamaru	Machilipatnam	Movva	Repairs to sub division at Movva	2.00
77	Krishna	Pamaru	Machilipatnam	Pamaru	Repairs to sub division at Pamaru	6.00
78	Krishna	Tiruvuru	Nuzvid	Tiruvuru	Repairs to sub division at Tiruvuru	2.00
79	Krishna	Vijayawada	Vijayawada	Vijayawada	Repairs & additional accomadation of QC Sub-Division office Building including lab at Vijayawada	8.00

<b>Sl. No.</b>	<b>District</b>	<b>Constituency</b>	<b>Division</b>	<b>Mandal</b>	<b>Name of the work</b>	<b>Est. Cost Rs. in Lakhs</b>
80	Krishna	Vijayawada	Vijayawada	Vijayawada	Repairs & additional accomadation of PIU Sub-Division office Building at Vijayawada	12.00
81	Krishna	Vijayawada	Vijayawada	Vijayawada	Repairs & additional accomadation of PRI Sub-Division office Building at Vijayawada	8.00
82	Krishna	Vijayawada	Vijayawada	Vijayawada	Repairs & additional accomadation of District level Cyclone Monitoring cell at Vijayawada	30.00
83	Krishna	Vijayawada	Vijayawada	Vijayawada	Repairs to QC Division Office Building at Vijayawada	5.00
84	Krishna	Vijayawada	Vijayawada	Vijayawada	Repairs to PR Division Office Building at Vijayawada	4.00
85	Nalgonda	Alair	Nalgonda-1	Alair	PRI Sub Division office at Alair	12.00
86	Nalgonda	NagarjunaSagar	Nalgonda	Anumula	PRI Sub Division office at Anumula	12.00
87	Nalgonda	Bhongir	Nalgonda-1	Bhongir	Sub Division QC lab and sub division office at Bhongir	18.00
88	Nalgonda	Huzurnagar	Nalgonda	Huzurnagar	PRI Sub Division & PIU Sub Division office at Huzurnagar	15.00
89	Nalgonda	Kodad	Nalgonda	Kodad	PRI Sub Division office at Kodad	12.00
90	Nalgonda	Munugode	Nalgonda	Munugode	Special Repairs to PRI Sub Division office at Munugode-	2.00
91	Nalgonda	Nakerekal	Nalgonda-1	Nakerekal	PRI Sub Division office at Nakrekal	12.00
92	Nalgonda	Nalgonda	Nalgonda-1	Nalgonda	Special Repairs to SE's office	5.00
93	Nalgonda	Tungathurthy	Nalgonda	Tungathurthy	PRI Sub Division office at Thungathurhtry	12.00
94	Prakasam	Addanki	Addanki	Addanki	Repairs to Sub-Division Office building @ Addanki	3.00
95	Prakasam	Chirala	Chirala	Chirala	Repairs to Sub-Division Office building @ Chirala	12.00

<b>Sl. No.</b>	<b>District</b>	<b>Constituency</b>	<b>Division</b>	<b>Mandal</b>	<b>Name of the work</b>	<b>Est. Cost Rs. in Lakhs</b>
96	Prakasam	Kandukur	Kandukur	Kandukur	Repairs & additional accomadation of QC Lab at Kandukur	18.00
97	Prakasam	Kanigiri	Kanigiri	Kanigiri	CDR to PR Sub -Division office building at Kanigiri	2.00
98	Prakasam	Kondepi	Kondepi	Kondepi	CDR to PR Sub -Division office building at Kondepi	2.50
99	Prakasam	Ongole	Ongole	Ongole	Repairs & additional accomadation of SN Padu Sub Division,V&QC Sub Division building at Ongole	30.00
100	Prakasam	Parchur	Parchu	Parchur	Repairs to Sub-Division Office building @ Parchur	2.00
101	Prakasam	Parchur	Martur	Parchur	Repairs to Section Office building @ Parchur	5.00
102	Prakasam	S.N.Padu	S.N.Padu	Chimakurthy	Repairs to Section Office building @ Chimakurthy	2.00
103	Prakasam	Y.Palem	Y.Palem	Y.Palem	Repairs & additional accomadation of PIU Subdivision office building at Y.Palem	12.00
104	Prakasam	Markapur	Markapur	Markapur	Repairs & additional accomadation of V& QC SUB DIVISION OFFICE at Markapur	18.00
105	Rangareddy	Hyderabad		Hyderabad	Repairs & additional accomadation of Disaster Management monitoring cell at ENC office,	200.00
106	S.P.S.R. Nellore	Gudur	Gudur	Chillakur	Repairs to cyclone Shelter at Posinavanipalem	0.20
107	S.P.S.R. Nellore	Gudur	Gudur	Chillakur	Repairs to cyclone Shelter at Momidi	0.25
108	S.P.S.R. Nellore	Gudur	Gudur	Chillakur	Repairs to cyclone Shelter at Mannegunta	0.25
109	S.P.S.R. Nellore	Gudur	Gudur	Chillakur	Repairs to cyclone Shelter at Kakuvaripalem	0.25
110	S.P.S.R. Nellore	Gudur	Gudur	Kota	Repairs to cyclone Shelter at Siddavarm	0.25
111	S.P.S.R. Nellore	Gudur	Gudur	Vakadu	Repairs to cyclone Shelter at Duggarajupatnam	0.25
112	S.P.S.R. Nellore	Gudur	Gudur	Vakadu	Repairs to cyclone Shelter at Valamedu	0.20
113	S.P.S.R. Nellore	Gudur	Gudur	Vakadu	Repairs to cyclone Shelter at Andanamala	0.20
114	S.P.S.R. Nellore	Gudur	Gudur	Vakadu	Repairs to cyclone Shelter at Kakivakam	0.20
115	S.P.S.R. Nellore	Gudur	Gudur	Vakadu	Repairs to cyclone Shelter at Nimmavanithippa	0.20
116	S.P.S.R. Nellore	Gudur	Gudur	Vakadu	Repairs to cyclone Shelter at Gagannapalem	0.20
117	S.P.S.R. Nellore	Gudur	Gudur	Vakadu	Repairs to cyclone Shelter at Nalgamala	0.20

<b>Sl. No.</b>	<b>District</b>	<b>Constituency</b>	<b>Division</b>	<b>Mandal</b>	<b>Name of the work</b>	<b>Est. Cost Rs. in Lakhs</b>
118	S.P.S.R. Nellore	Gudur	Gudur	Vakadu	Repairs to cyclone Shelter at Busapalem	0.20
119	S.P.S.R. Nellore	Gudur	Gudur	Vakadu	Repairs to cyclone Shelter at Reddypalem	0.20
120	S.P.S.R. Nellore	Gudur	Gudur	Vakadu	Repairs to cyclone Shelter at Chebetivaripalem	0.20
121	S.P.S.R. Nellore	Gudur	Gudur	Vakadu	Repairs to cyclone Shelter at Thupilipalem	0.20
122	S.P.S.R. Nellore	Gudur	Gudur	Vakadu	Repairs to cyclone Shelter at Mulapadava	0.20
123	S.P.S.R. Nellore	Indukurupet	Nellore	Indukurupet	Repairs to cyclone Shelter at East Pattapupalem of Mypadu	2.50
124	S.P.S.R. Nellore	Indukurupet	Nellore	Indukurupet	Repairs to cyclone Shelter at Gangapatnam (KM Kandriga)	2.50
125	S.P.S.R. Nellore	Kavali	Kavali	Allur	Repairs to cyclone Shelter at Galidibbalu	1.30
126	S.P.S.R. Nellore	Kavali	Kavali	Allur	Repairs to cyclone Shelter at Kothakurru Pattapupalem	1.20
127	S.P.S.R. Nellore	Kavali	Kavali	Allur	Repairs to cyclone Shelter at Labbipalem of Iskapalli	1.50
128	S.P.S.R. Nellore	Kavali	Kavali	Allur	Repairs to cyclone Shelter at Sambhunipalem of Iskapalli	0.80
129	S.P.S.R. Nellore	Kavali	Kavali	Allur	Repairs to cyclone Shelter at Purini H.W	1.00
130	S.P.S.R. Nellore	Kavali	Kavali	Allur	Repairs to cyclone Shelter at East Gogulapalli H.W	1.00
131	S.P.S.R. Nellore	Kavali	Kavali	Allur	Repairs to cyclone Shelter at East GogulapalliMain village	1.00
132	S.P.S.R. Nellore	Kavali	Kavali	Bogole	Repairs to cyclone Shelter at Sambasivapuram	1.00
133	S.P.S.R. Nellore	Kavali	Kavali	Bogole	Repairs to cyclone Shelter at Siddavaram (Siddannapalem )	1.00
134	S.P.S.R. Nellore	Kavali	Kavali	Bogole	Repairs to cyclone Shelter at Allimadugu	1.20
135	S.P.S.R. Nellore	Kavali	Kavali	Bogole	Repairs to cyclone Shelter at Mallayapalem	1.00
136	S.P.S.R. Nellore	Kavali	Kavali	Bogole	Repairs to cyclone Shelter at S.V.Palem	1.00
137	S.P.S.R. Nellore	Kavali	Kavali	Bogole	Repairs to cyclone Shelter at Kotha Bangarupalem	1.30
138	S.P.S.R. Nellore	Kavali	Kavali	Kavali	Repairs to cyclone Shelter at Chennayapalem	1.50
139	S.P.S.R. Nellore	Kavali	Kavali	Kavali	Repairs to cyclone Shelter at Nandempuram	1.00
140	S.P.S.R. Nellore	Kavali	Kavali	Kavali	Repairs to cyclone Shelter at Pallipalem of Chennayaalem	2.50

<b>Sl. No.</b>	<b>District</b>	<b>Constituency</b>	<b>Division</b>	<b>Mandal</b>	<b>Name of the work</b>	<b>Est. Cost Rs. in Lakhs</b>
141	S.P.S.R. Nellore	Kavali	Kavali	Kavali	Repairs to cyclone Shelter at Pedapattapupalem (Pallipalem)	2.00
142	S.P.S.R. Nellore	Kavali	Kavali	Kavali	Repairs to cyclone Shelter at Rudrukota	1.00
143	S.P.S.R. Nellore	Kavali	Kavali	Kavali	Repairs to cyclone Shelter at Anemadugu	1.00
144	S.P.S.R. Nellore	Kavali	Kavali	Kavali	Repairs to cyclone Shelter at Ramachandrapuram	1.00
145	S.P.S.R. Nellore	Kavali	Kavali	Kavali	Repairs to cyclone Shelter at Thummalapenta Pattapupalem	1.00
146	S.P.S.R. Nellore	Kavali	Kavali	Kavali	Repairs to cyclone Shelter at Kothasatram Pattapupalem	2.00
147	S.P.S.R. Nellore	Kavali	Kavali	Kavali	Repairs to cyclone Shelter at Kothasatram	1.00
148	S.P.S.R. Nellore	Kavali	Kavali	Kavali	Repairs to cyclone Shelter at Puvuladoruvu	1.00
149	S.P.S.R. Nellore	Kavali	Kavali	Kavali	Repairs to cyclone Shelter at Nattupattapupalem	1.00
150	S.P.S.R. Nellore	Kavali	Kavali	Kavali	Repairs to cyclone Shelter at Mamilladoruvu	1.00
151	S.P.S.R. Nellore	Kavali	Kavali	Kavali	Repairs to cyclone Shelter at Nadimpalli	2.00
152	S.P.S.R. Nellore	Kavali	Kavali	Kavali	Repairs to cyclone Shelter at Votturu	1.50
153	S.P.S.R. Nellore	Kavali	Kavali	Kavali	Repairs to cyclone Shelter at Venkateswarapuram	1.60
154	S.P.S.R. Nellore	Kavali	Kavali	Kavali	Repairs to cyclone Shelter at Lakshmipuram	2.50
155	S.P.S.R. Nellore	Kavali	Kavali	Kavali	Repairs to cyclone Shelter at Mannangidinne	1.00
156	S.P.S.R. Nellore	Kavali	Kavali	Kavali	Repairs to cyclone Shelter at Thallapalem	1.00
157	S.P.S.R. Nellore	Kavali	Kavali	Kavali	Repairs to cyclone Shelter at Annagaripalem	1.00
158	S.P.S.R. Nellore	Kavali	Kavali	Kavali	Repairs to cyclone Shelter at Konetipalem	1.50
159	S.P.S.R. Nellore	Kavali	Kavali	Kavali	Repairs to cyclone Shelter at Gummadi Bondala	1.00
160	S.P.S.R. Nellore	Kovur	Nellore	Vidavalur	Repairs to cyclone Shelter at Navayuga Nagar	0.50
161	S.P.S.R. Nellore	Kovur	Nellore	Vidavalur	Repairs to cyclone Shelter at Indira Nagar	0.75
162	S.P.S.R. Nellore	Kovur	Nellore	Vidavalur	Repairs to cyclone Shelter at Kancharapalem HW	1.50
163	S.P.S.R. Nellore	Kovur	Nellore	Vidavalur	Repairs to cyclone Shelter at Bhadrachalam	0.60
164	S.P.S.R. Nellore	Kovur	Nellore	Vidavalur	Repairs to cyclone Shelter at Ramachandrapuram	1.00
165	S.P.S.R. Nellore	Kovur	Nellore	Vidavalur	Repairs to cyclone Shelter at Busagadipalem	1.00
166	S.P.S.R. Nellore	Kovur	Nellore	Vidavalur	Repairs to cyclone Shelter at Ponnapudi	1.00
167	S.P.S.R. Nellore	Kovur	Nellore	Vidavalur	Repairs to cyclone Shelter at Vekatanarayananapuram	0.75
168	S.P.S.R. Nellore	Kovur	Nellore	Vidavalur	Repairs to cyclone Shelter at Lakshmipuram	0.60
169	S.P.S.R. Nellore	Kovur	Nellore	Kodavalur	Repairs to cyclone Shelter at Damegunat	0.60

<b>Sl. No.</b>	<b>District</b>	<b>Constituency</b>	<b>Division</b>	<b>Mandal</b>	<b>Name of the work</b>	<b>Est. Cost Rs. in Lakhs</b>
170	S.P.S.R. Nellore	Sarvepalli	Nellore	T.P.Gudur	Repairs to cyclone Shelter at Pathapattapupalem of Kodur (old)	3.00
171	S.P.S.R. Nellore	Sarvepalli	Nellore	T.P.Gudur	Repairs to cyclone Shelter at Pathapattapupalem of Kodur (New)	0.90
172	S.P.S.R. Nellore	Sarvepalli	Nellore	T.P.Gudur	Repairs to cyclone Shelter at Venkannapalem Kothapattapupalem	2.30
173	S.P.S.R. Nellore	Sarvepalli	Nellore	T.P.Gudur	Repairs to cyclone Shelter at Gollapalem of Mandapam	2.50
174	S.P.S.R. Nellore	Sarvepalli	Nellore	T.P.Gudur	Repairs to cyclone Shelter at Venkannapalem Girijana Colony	0.62
175	S.P.S.R. Nellore	Sarvepalli	Nellore	T.P.Gudur	Repairs to cyclone Shelter at Venkateswara Pattapupalem	2.50
176	S.P.S.R. Nellore	Sarvepalli	Nellore	T.P.Gudur	Repairs to cyclone Shelter at Koduru Kothapattapupalem	2.30
177	S.P.S.R. Nellore	Sarvepalli	Nellore	T.P.Gudur	Repairs to cyclone Shelter at Edur Bit-I (Katepalli)	3.75
178	S.P.S.R. Nellore	Sarvepalli	Nellore	T.P.Gudur	Repairs to cyclone Shelter at Iskadoruvu Pattapupalem	2.50
179	S.P.S.R. Nellore	Sarvepalli	Nellore	T.P.Gudur	Repairs to cyclone Shelter at Pengoludibba	2.50
180	S.P.S.R. Nellore	Sarvepalli	Nellore	T.P.Gudur	Repairs to cyclone Shelter at Thanduvarigunta	2.30
181	S.P.S.R. Nellore	Sarvepalli	Nellore	T.P.Gudur	Repairs to cyclone Shelter at Koduru Kandriga	2.30
182	S.P.S.R. Nellore	Sarvepalli	Nellore	T.P.Gudur	Repairs to cyclone Shelter at Nadimipattapupalem of Kodur	2.50
183	S.P.S.R. Nellore	Sarvepalli	Nellore	T.P.Gudur	Repairs to cyclone Shelter at Kodur Harijanawada	2.30
184	S.P.S.R. Nellore	Sarvepalli	Nellore	T.P.Gudur	Repairs to cyclone Shelter at Gamallapalem of Kodur	2.00
185	S.P.S.R. Nellore	Sarvepalli	Nellore	T.P.Gudur	Repairs to cyclone Shelter at Venkannapalem Mixed Colony	2.00
186	S.P.S.R. Nellore	Sarvepalli	Nellore	T.P.Gudur	Repairs to cyclone Shelter at Mallikarjunapuram	2.30
187	S.P.S.R. Nellore	Sarvepalli	Nellore	Muthukur	Repairs to cyclone Shelter at Bodiswamikandriga	0.61
188	S.P.S.R. Nellore	Sarvepalli	Nellore	Muthukur	Repairs to cyclone Shelter at Mallur	1.25
189	S.P.S.R. Nellore	Sarvepalli	Nellore	Muthukur	Repairs to cyclone Shelter at Epur	1.25

<b>Sl. No.</b>	<b>District</b>	<b>Constituency</b>	<b>Division</b>	<b>Mandal</b>	<b>Name of the work</b>	<b>Est. Cost Rs. in Lakhs</b>
190	S.P.S.R. Nellore	Sarvepalli	Nellore	Muthukur	Repairs to cyclone Shelter at Dibbameda Harijanawada	0.30
191	S.P.S.R. Nellore	Sarvepalli	Nellore	Muthukur	Repairs to cyclone Shelter at Nadimipattapupalem of Krishnapatnam	0.83
192	S.P.S.R. Nellore	Gudur	Gudur	Manubolu	Repairs to cyclone Shelter at Manubollu (Repairs to Guest house)	10.00
193	S.P.S.R. Nellore	Sullurupeta	Gudur	D.V.Satram	Repairs to cyclone Shelter at Karikadu	0.20
194	S.P.S.R. Nellore	Sullurupeta	Gudur	D.V.Satram	Repairs to cyclone Shelter at Velukadu	0.20
195	S.P.S.R. Nellore	Sullurupeta	Gudur	Sullurupet	Repairs to cyclone Shelter at Koradi	0.50
196	S.P.S.R. Nellore	Sullurupeta	Gudur	Sullurupet	Repairs to cyclone Shelter at Perinadu	0.20
197	Srikakulam	Etcherla	Srikakulam	Kotabommali	Repairs & additional accomadation of PIU subdivision at Kotabommali	12.00
198	Srikakulam	Itchapuram	Palasa	Sompeta	Repairs & additional accomadation of PIU sub diviiosn office at Sompeta	12.00
199	Srikakulam	Palkonda	Srikakulam	Palkonda	Repairs & additional accomadation of QC lab at Palkonda	18.00
200	Srikakulam	Rajam	Srikakulam	Rajam	Repairs & additional accomadation of PIU subdivision at Rajam	12.00
201	Srikakulam	Srikakulam	Srikakulam	Srikakulam	Const. of PIU subdivision,QC lab building at Srikakulam	30.00
202	Visakhapatnam	Anakapalli	Visakhapatnam	Anakapalli	Repairs & additional accomadation of Sub-Division office building @ Anakapalli	12.00
203	Visakhapatnam	Chodavaram	Visakhapatnam	Chodavaram	Repairs & additional accomadation of Sub-Division office building @ Chodavaram	12.00
204	Visakhapatnam	Narsipatnam	Visakhapatnam	Narsipatnam	Repairs & additional accomadation of Sub-Division office building @ Narasipatnam	12.00
205	Visakhapatnam	Paderu	Visakhapatnam	Paderu	Repairs & Additional accomadatin at Paderu	18.00
206	Visakhapatnam	Sabbavaram	Visakhapatnam	Sabbavaram	Repairs & additional accomadation of Sub-Division office building @ Sabbavaram	12.00

<b>Sl. No.</b>	<b>District</b>	<b>Constituency</b>	<b>Division</b>	<b>Mandal</b>	<b>Name of the work</b>	<b>Est. Cost Rs. in Lakhs</b>
207	Visakhapatnam	Visakhapatnam	Visakhapatnam	Visakhapatnam	Repairs & additional accomadation of QC Sub Division & lab building at Visakhapatnam	18.00
208	Vizianagaram	Cheepurupalli	Vizianagaram	Cheepurupalli	Repairs & additional accomadation of P.R.SUB DIVISION OFFICE at Cheepurupalli	12.00
209	Vizianagaram	Parvatipuram	Parvatipuram	Parvatipuram	Repairs & additional accomadation of QC labcum office at Parvathipuram	18.00
210	Vizianagaram	Vizianagaram	Vizianagaram	Vizianagaram	Repairs & additional accomadation of QC lab at Vizianagaram	18.00
211	Vizianagaram	Vizianagaram	Vizianagaram	Vizianagaram	Repairs & additional accomadation of ZP Guest house at Vizianagaram	30.00
212	Vizianagaram			Alugolu	CDR to Hostel building at Alugolu	17.00
213	West Godavari	Bhimavaram	Narsapuram	Bhimavaram	Repairs & additional accomadation of PRI Sub Division Office building at Bhimavaram	12.00
214	West Godavari	Eluru	Eluru	Eluru	Repairs & additional accomadation of Sub Division, QC Sub Division & lab at Eluru	30.00
215	West Godavari	Nidadavole	Narsapuram	Undrajavaram	Repairs & additional accomadation of PRI Sub Division Office building at Undrajavaram	12.00
216	West Godavari	Palakol	Narsapuram	Palakol	Repairs & additional accomadation of PRI Sub Division Office building at Palakol	12.00
217	West Godavari	Tanuku	Eluru	Tanuku	Repairs & additional accomadation of PRI Sub Division Office at Tanuku	12.00
218	West Godavari	Undi	Narsapuram	Akividu	Repairs & additional accomadation of PRI Sub Division Office building at Akividu	12.00
219	West Godavari	Unguturu	Eluru	Bhimadole	Repairs & additional accomadation of PRI Sub Division Office at Bhimadole	12.00
220	West Godavari	Tanuku		Tanuku	Restoration of community hall in SC area Duvva (V) of Tanuku(M)	12.50
					<b>Total</b>	<b>1560.16</b>

M.V.P.C.SASTRY  
SPECIAL CHIEF SECRETARY TO GOVERNMENT